

Figure 1




Figure 2




Figure 3A




Figure 3B




Figure 4A




Figure 4B

7/45




Figure 4C




Figure 4D

	00	01	10	11	<b>504</b>
11	0.95 V <sub>н</sub>	0.90 V <sub>H</sub>	0.90 V <sub>H</sub>	0	
10	0.90 V <sub>H</sub>	0.95 V <sub>H</sub>	0	0.90 V <sub>H</sub>	
01	0.90 V <sub>H</sub>	0	0.95 V <sub>H</sub>	0.90 V <sub>H</sub>	
00	0	0.90 V <sub>H</sub>	0.90 V <sub>H</sub>	0.95 V <sub>H</sub>	
502		I	<u> </u>	I	J

Figure 5




Figure 6




Figure 7A

12/45




Figure 7B




Figure 7C

14/45




Figure 7D




Figure 8




Figure 9




Figure 10





Figure 11



Figur 12A




Figure 12B




Figure 12C




Figure 12D

	00	01	10	11
11	0.95 V <sub>H</sub>	0.95 V <sub>H</sub>	0.95 V <sub>H</sub>	0
10	0.95 V <sub>H</sub>	0.95 V <sub>H</sub>	0	0.95 V <sub>H</sub>
01	0.95 V <sub>H</sub>	0	0.95 V <sub>H</sub>	0.95 V <sub>H</sub>
00	0	0.95 V <sub>H</sub>	0.95 V <sub>H</sub>	0.95 V <sub>H</sub>

Figure 13




Figure 14




Figure 15A




Figure 15B




Figure 15C




Figure 15D

	00	01	10	11	
11	0.95 V <sub>H</sub>	0.95 V <sub>H</sub>	0.95 V <sub>H</sub>	0	
10	0.95 V <sub>H</sub>	0.95 V <sub>H</sub>	0	0.95 V <sub>H</sub>	
01	0.95 V <sub>H</sub>	0	0.90 V <sub>H</sub>	0.90 V <sub>H</sub>	1602 1604
00	0	0.95 V <sub>H</sub>	0.95 V <sub>H</sub>	0.95 V <sub>H</sub>	

Figure 16






Figure 17

	00	01	10	11
11	0.90 V <sub>H</sub>	0.95 V <sub>H</sub>	0.90 V <sub>H</sub>	0
10	0.95 V <sub>H</sub>	0.95 V <sub>H</sub>	0	0.95 V <sub>H</sub>
01	0.95 V <sub>H</sub>	0	0.90 V <sub>H</sub>	0.90 V <sub>H</sub>
00	0	0.95 V <sub>H</sub>	0.95 V <sub>H</sub>	0.95 V <sub>H</sub>

Figure 18




Figure 19

	00	01	10	11
11	0.90 V <sub>H</sub>	0.95 V <sub>H</sub>	0.90 V <sub>H</sub>	0
10	0.95 V <sub>H</sub>	0.90 V <sub>H</sub>	0	0.90 V <sub>H</sub>
01	0.95 V <sub>H</sub>	0	0.90 V <sub>H</sub>	0.90 V <sub>H</sub>
00	0	0.95 V <sub>H</sub>	0.95 V <sub>H</sub>	0.95 V <sub>H</sub>

Figure 20








Figure 21

	00	01	10	11
11	0	0.90 V <sub>H</sub>	0.90 V <sub>H</sub>	0
10	0.95 V <sub>H</sub>	0.90 V <sub>H</sub>	0	0.90 V <sub>H</sub>
01	0.95 V <sub>H</sub>	0	0.90 V <sub>H</sub>	0.90 V <sub>H</sub>
00	0	0.95 V <sub>H</sub>	0.95 V <sub>H</sub>	0.95 V <sub>H</sub>

Figure 22



37/45






Figure 23B




Figure 24A




Figure 24B




Figure 25





Figure 26A

41/45






Figure 27





Figure 28

44/45



45/45

